



Certificate

Breakthrough Management Quality Registrar (BMQR)

Certifies that the Quality requirement of Diesel Engines – NOx Reduction Agent AUS 32: Part 1: of

QBLUE FLUID PVT LTD

Office: No. 195-B, 32nd Street, Rahmath Nagar, Palayamkottai,
Tirunelveli – 627 002. Tamilnadu, India.

Factory: No. 360/8 B, CSI Church Street, Thuraiyur,
Tirunelveli – 627 358. Tamilnadu, India.

has tested their product at M/S. NAWAL Analytical Laboratories, an ISO/IEC 17025:2017 accredited laboratory. The test method used for testing is in accordance with

ISO 22241-2:2019

DIESEL ENGINES – NOX REDUCTION AGENT AUS32 – TEST METHODS

for the following scope of certification

MANUFACTURE AND SUPPLY OF DIESEL EXHAUST FLUID

The Product was tested by client on a voluntary basis and complies with the essential requirements of ISO 22241-1:2019 wide test Report No:TC583421000040785

Further clarifications regarding the scope of this certificate and applicability of ISO 22241-2:2019 requirements may be obtained by consulting the organization.

Original Certification Date : 23/11/2021
Current Certification Date : 23/11/2021
First Surveillance Due on : 22/11/2022
Second Surveillance Due on : 22/11/2023
Certificate Expiration Date : 22/11/2024

Surveillance Audit

Due On 22/11/2022 Due On 22/11/2023



This certificate is invalid if surveillance audit is not completed



Certificate No: IS222IS211942



For BMQR

No:5, 2nd Floor, Sathyamoorthy Road, Thiruvalléeswarar Nagar, Thirumangalam,
Anna Nagar West, Chennai - 600 040. Tamilnadu, India.
email: iso@bmqr.com, Web : www.bmqr.com

PH- 044-26152595

The certificate will remain current subject to the company maintaining its system to the required standard(s). This will be monitored regularly by BMQR Certifications Pvt. Ltd., This Certification details and effectiveness are listed at www.bmqr.com. Registration does not assure the quality of products produced by a Quality System. This Certificate is granted based on the limited sampling audit as per ISO 19011:2011 and BMQR is not responsible for client's failure to maintain documented quality system. This certificate is the property of BMQR Certifications Pvt. Ltd, and to be returned upon request.